

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director GARY R. HERBERT Lieutenant Governor

OGM Steve Demczak Environmental Scientist III

Company Dennis Oakley Environmental Engineer

4015/017 Internal & Inspection Report

Permit Number:	C0150017
Inspection Type:	PARTIAL
Inspection Date:	Monday, June 22, 2009
Start Date/Time:	6/22/2009 10:00:00 AM
End Date/Time:	6/22/2009 1:00:00 PM
Last Inspection:	Wednesday, May 27, 2009

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 70's

InspectionID Report Number: 2046

Accepted by: jhelfric

7/9/2009

Permitee: PACIFICORP

JON M. HUNTSMAN, JR. Governor

Operator: ENERGY WEST MINING CO

Site: DES BEE DOVE MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

	Total Permitted			
36.02	Total Disturbed			
	Phase I			
	Phase II			
	Phase III			

Current Acreages

Mineral Ownership

Federal

State

✓ Fee

Other

Types of Operations

✓ Underground

Surface

County

☐ Loadout ☐ Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

The permittee fix some rills on the trail to the top of the mountain.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Tuesday, June 23, 2009

Inspector ID Number: 39

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, June 22, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	V		V	<u>_</u> _
4.a	Hydrologic Balance: Diversions	✓		<u> </u>	<u> </u>
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		П		
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	<u> </u>		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	V		<u> </u>	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	V		<u> </u>	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	<u> </u>			
	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance		— <u>—</u>		
	Other				
				니	

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, June 22, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit will expire on Aug.30, 2010.

2. Signs and Markers

The identification sign is located on the trail to the property. Information contained the information required in the R645 Coal Rules.

3. Topsoil

All topsoil was used in reclamation. There were no signs of erosion on the reclaimed lands.

4.a Hydrologic Balance: Diversions

Diversions were spot-check and there were no signs of failure or sediment build-up.

8. Noncoal Waste

The reclaim site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or damage was noticed during the inspection.

12. Backfilling And Grading

The mine site is completely backfilled and graded.

18. Support Facilities, Utility Installations

There are no facilities.